Best Available Copy



SLANTING DESIGN: A Pilot Program

FINAL REPORT

October 1985

FOR: The Federal Emergency Management Agency

Washington, DC 20472

Contract No. EMW-C-0705

Work Unit No. 1622B

Approved for Public Release

Distribution Unlimited

20030/21024



SLANTING DESIGN: A Pilot Program

FINAL REPORT SUMMARY

October 1985

FOR: The Federal Emergency Management Agency

Washington, DC 20472

Contract No. EMW-C-0705

Work Unit No. 1622B

Approved for Public Release

Distribution Unlimited

by Alexander Shaw

American Institute of Architects Foundation

"This report has been reviewed in the Federal Emergency Management Agency and approved for publication. Approval does not signify that the contents necessarily reflect the views and policies of the Federal Emergency Management Agency."

REPRODUCTION QUALITY NOTICE

This document is the best quality available. The copy furnished to DTIC contained pages that may have the following quality problems:

- · Pages smaller or larger than normal.
- · Pages with background color or light colored printing.
- Pages with small type or poor printing; and or
- Pages with continuous tone material or color photographs.

Due to various output media available these conditions may or may not cause poor legibility in the microfiche or hardcopy output you receive.

If this block is checked, the copy furnished to DTIC
contained pages with color printing, that when reproduced in
Black and White, may change detail of the original copy.

FINAL REPORT: SUMMARY

The Federal Emergency Management Agency (FEMA) under the mandate of the U.S. Congress created a pilot program to investigate the practical and cost implications of a national sianting shelter construction program. The availability of such shelters would make a critical workforce concept more viable. The intention was to incorporate shelter areas into buildings in such a manner that the affected spaces would continue to fully serve their intended functional purposes. An additional objective was to evaluate existing slanting design guidance materials, assessing their usefulness to the broad spectrum of practicing architects and engineers.

A case study method was deemed most useful for the project. The AIA Foundation (AIAF) surveyed local architectural firms and found Mariani and Associates to have two appropriate projects with building owners who were willing to entertain the possibility of shelter construction. Mariani was hired and the project begun. An office building and a hospital, both in the Washington, D.C. area were selected. Each building had a non drive-in basement with three floors of structure above. The process of design, construction documents, cost estimates, and construction were observed. Models of the hospital shelter were tested for structural integrity.

The office building was located in downtown Washington at 727 15th Street, N.W., just two blocks from the White House and the Treasury Building. The project involved the demolition of a single story movie theater and the restoration and incorporation of its historic facade into a new eleven-story office structure.

38

The original hospital project was located at 13th and V Streets, N.W. on a 2.4 acre full block site. Parts of an existing complex were to have been renovated and parts demolished to allow for new construction. The two projects represented a wide cross-section of the types of problems and impediments which might be encountered in a national scale construction program.

The design of the shelter in the office building was straightforward because the program and plan were simple. Major problems
were of three types; structural, financial and approval related.
The structural difficulty involved the fact that the added
dimension required for the floor and ceiling of the shelter
necessitated taking the shoring and footings below those of the
two adjacent buildings. The additional costs associated with
this were not directly related to the construction of the shelter
and eventually led to the decision not to construct. The
financial problems were related to the sluggish economic climate
which existed. The speculative developers proceeded quite slowly
hoping to acquire more favorable loan monies. The approval

to both the Fine Arts and Landmarks Commissions several times, with each submittal extending the design process.

Four alternative designs were considered for the hospital located at 13th and V Streets. A design was selected and detailed, construction documents were prepared and submitted to federal financing agencies only to lead to a complete change of site and total redesign of the project. On the new site the design proceeded simply, the shelter was located in an auditorium below the main entrance to the hospital. Detailed design, structural calculations, construction bids, and contractor selection were all completed. Problems and delays were caused by a change of ownership of the hospital, a labor strike, and a legal dispute related to an adjacent parking structure. Construction difficulties were minimal. The blast shelter added a new layer of complexity which necessitated additional planning and scheduling but no extraordinary constraints.

Construction cost estimates for the two projects ranged between \$37 and \$110 per square foot. No definitive explanation for this wide range can be offered.

The design guidance materials used in this project were found to provide accurate information but to be inadequate for use in the type of national construction program envisioned with the critical workforce concept. *Protective Construction*, TR-20,

(Vol.4) and the other documents were judged to be more textbooks than design manuals; requiring reference to other documents to clarify definitions, terminology, and symbols. The ideal design manual should present straightforward examples, problems and many charts and tables to assist the busy, and probably inexperienced designer.

Two models (at one-fifth scale) of the hospital shelter were constructed and tested. One model was exposed to 15 psi over-pressure, as designed. This model suffered no damage. The second model was exposed to 50 psi overpressure and suffered only minor damage in the form of hairline cracking.

Conclusions are threefold:

- A national shelter construction program is thought to be feasible, but precise project scheduling would be extremely difficult.
- Existing design guidance is thought to be inadequate.
 No national construction program should be contemplated prior to the preparation of simplified, straightforward design manuals.
- No firm assessments of the costs of a national construction program can be made.

Street NW. Incremental shelter construction cost estimates ranged between


\$37 and \$110 per square foot above normal costs.

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

<u>see reverse side</u>

Evaluation were performed for two questions: (1) the adequacy of design gridance provided to practicing architects and engineers by "Protective Construction", TR-20 (Vol.4), and other existing references -- Found to be inadequate; and (2) the practical difficulties of incorporating shelter construction into otherwise typical building projects -- Found to be manageable, but difficult to schedule precisely.

The shelters were designed to sustain 15 psi (pounds per square inch) overpressure. Fifth scale models of the NRH shelter were tested at White Sands, NM in July 1935 at overpressures of 15 psi and 50 psi. The model tested at 50 psi sustained only very minor damage in the form of hairline cracks. The model tested at 15 psi sustained no apparent damage.



SLANTING DESIGN: A Pilot Program

FINAL REPORT

October 1985

FOR: The Federal Emergency Management Agency

Washington, DC 20472

Contract No. EMW-C-0705

Work Unit No. 1622B

Approved for Public Release

Distribution Unlimited

by Alexander Shaw

American Institute of Architects Foundation

[&]quot;This report has been reviewed in the Federal Emergency Manangement Agency and approved for publication. Approval does not signify that the contents necessarily reflect the views and policies of the Federal Emergency Management Agency."

FINAL REPORT: SLANTING SHELTER DESIGN

TABLE OF CONTENTS	PAGE
List of Figures	2
Abstract	4
Final Report:	5
Objectives	5
Methods	6
Discussion of Research	7
Architect Selection	7
Site Selection	8
Design Process	12
Office Building - 727 15th Street, NW	12
Hospital - 106 Irving Street, NW	18
Construction	39
Use of TR-20	52
Model Test	57
Conclusions & Recommendations	68
APPENDICES:	
A. Preliminary Structural Calculations - Hospital Shelter	70
B. Final Structural Calculations - Hospital Shelter	76

LIST OF FIGURES	PAGE
1. Architect's Sketch of Office Facade 727 15th Street	9
2. Preliminary Plan of Office Basement	11
3. Developer's Advertisement with Completed Facade	16
727 15th Street	
4. Hospital Alternative #1 First Basement Plan	17
5. Hospital Alternative #2 Shelter Plan	19
6. Hospital Alternative #2 Sections & Elevation	20
7. Hospital Alternative #2 First Basement Plan	21
8. Hospital Alternative #2 Second Basement Plan	22
9. Hospital Alternative #3 First Floor Plan	23
10. Hospital Alternative #4 Shelter Plan	25
11. Hospital Alternative #4 Sections & Elevation	26
12. Hospital Alternative #4 First Basement Plan	27
13. Hospital Alternative #4 Second Basement Plan	2ა
14. Hospital Alternative #5 [FINAL] First Floor Plan	30
15. Preliminary Construction Bid Turner	31
16. Structural Details Sections	32
17. Structural Details Basement Plan	33
18. Structural Details First Floor Plan	34
19. Structural Details Beam Details	35
20. Structural Details Column Details	36
21. Final Construction Bid Turner	37
22. Final Construction Bid Hyman	33
23. Hospital Construction Site Preparation	40
24. Hospital Construction Site Preparation	41

		40
25.	Hospital Construction South Wall of Shelter	42
26.	Hospital Construction Footing Preparation	43
27.	Hospital Construction Adjacent Story	44
28.	Hospital Construction Concrete Formwork	45
29.	Hospital Construction Footing Poured	46
30.	Hospital Construction Column Reinforcing Steel	47
31.	Hospital Construction Beam Reinforcing Steel	48
	Beam/Footing Connection Details	50
	TR20 (Volume 4) Evaluation - Neubauer	54
	TR20 (Volume 4) Evaluation - Cutts	55
	Design Guidance Reference List	56
	Blast Test of Model Front & Side of Shelter	53
	Blast Test of Model Rear & Side of Shelter	59
	Interior of Hospital Shelter	60
	Hospital Shelter in Place Before Back Filling	61
	Hospital Shelter at 15 psi Level After Back Filling	62
	Hospital Shelter at 50 psi Level After Back Filling	63
	View of Hospital Shelter at 50 psi Level	64
	Post-Blast View of Hospital Shelter at 15 psi Leve	65
47.	Showing No Cracks	
4.4	Post-Blast View of Hospital Shelter at 50 psi Level	66
~~ .	Showing Hairline Cracks on Roof	-
45		67
→ ノ.	Showing Hairline Cracks	- •
	SUDMING LIGHT OF SCHOOL	

ABSTRACT

The AiA Foundation contracted with Mariani and Associates to design basement blast shelter areas in two buildings in Washington, D.C. Alternate construction bids were received for both designs. FEMA decided to finance shelter construction at the National Rehabilitation Hospital (NRH) located at 106 Irving Street, N.W. and not to finance shelter construction at 727 15th Street, N.W. Incremental shelter construction cost estimates ranged between \$37 and \$110 par square foot above normal costs.

Evaluations were performed for two questions: (1) the adequacy of design guidance provided to practicing architects and engineers by "Protective Construction", TR-20 (Vol. 4), and other existing references -- Found to be inadequate; and (2) the practical difficulties of incorporating shelter construction into otherwise typical building projects -- Found to be manageable, but difficult to schedule precisely.

The shelters were designed to sustain 15 psi (pounds per square inch) overpressure. Fifth scale models of the NRH shelter were tested at White Sands, N.M. in July, 1985, at overpressures of 15 psi and 50 psi. The model tested at 50 psi sustained only very minor damage; in the form of hairline cracks. The model tested at 15 psi sustained no apparent damage.

OBJECTIVES

The United States Congress mandated in the 1981 Defense Appropriations Act that the Federal Emergency Management Agency (FEMA) create a pilot program to investigate the practical and cost implications of a national shelter construction program. The pilot program was to consist of designing and constructing a minimum of two buildings with an enhanced ability to withstand nuclear explosions while sustaining minimized damage. program was an approach to maximizing nuclear effects protection in risk areas in the United States and was to provide shelters which are strong enough to survive high overpressure (above 15 The availability of such shelters would make a critical psi), work force concept more viable. The major objective of the effort was to measure the additional costs and to assess the practical difficulties associated with the design and construction of buildings that incorporate current slanting design and blast resistance guidance. The intention was to incorporate shelter areas into buildings in such a manner that the affected spaces would continue to be fully functional still serving their original purposes.

An additional objective was to evaluate the efficacy and usefulness of existing stanting shelter design guidance for such a national shelter construction program as would be required to sustain the critical workforce concept. A case study method was deemed most useful.

- 1. The shelters were to be designed and constructed in buildings which did not have drive-in basements.
- 2. The AIA Foundation (AIAF) searched for and identified two commercial buildings (a hospital and an office) in the Washington, D.C. area for which basements were planned.
- 3. The AIAF contracted with Mariani and Associates who were the architects of both buildings.
- 4. Mariani obtained the approval of the building owners for the inclusion of the alternative shelter designs in the two projects.
- 5. Several alternative shelter locations were selected and presented to FEMA.
- 6. Final shelter locations were selected and designs created.
- 7. Engineering calculations and construction documents for the shelter areas were prepared.
- 8. Construction bids were requested for the shelters as alternates to the base bids for the building construction.
- 9. Yes/No construction decisions were made for both shelters.
- 10. Construction of the hospital shelter was begun and completed.
- 11. Waterways Experiment Station under a separate contract to FEMA constructed two fifth-scale models of the hospital shelter. One model was blast-tested at 15 psi overpressure; the other at 50 psi.

DISCUSSION OF RESEARCH:

Selection of Architects:

At the outset of the project, October 1981, the AIA Foundation performed a survey of architectural firms in the Washington, D.C. metropolitan area to find what types of projects they had underway. AIAF was looking for commercial buildings planned to have a minimum of three stories above grade. The buildings were to have basements which were not of the drive~in type. The building projects were required to be at a preliminary design stage so that incorporation of alternate slanting shelter design would not disrupt the schedule or increase costs to the building owner or developer.

The firm of Mariani and Associates, inc., located at 1600 20th Street, N.W. was found to have two such projects at that time. The firm also had considerable shelter design expertise from previous work and was judged to be an appropriate subcontractor to work on the project. Mariani requested and received tentative approval from its clients to use the two buildings as the case studies in this project. An AIAF subcontract was subsequently written with Mariani.

Selection of Building Sites:

The two selected bu'iding projects were a speculative office building and an addition to a hospital. The office building was located in downtown Washington at 727 15th Street, N.W., just two blocks from the White House and the Treasury building. The project involved the demolition of a single story movie theater and the restoration and incorporation of its historic facade into a new eleven-story office building with basement level below (see Figure 1). The building was planned to have a reinforced concrete structure and contain a total of 50,500 square feet of office and ground floor commercial space. The basement area was to be 4,500 square feet and because no parking was planned, more than one underground level could have been designed as shelter area should that have proven desirable.

The hospital project, the National Rehabilitation Hospital, was located at 13th and V Streets, N.W. on a 2.4 acre full block site. Of the existing building complex, the structures on the northern portion of the site were to be renovated, while those on the southern portion were to be razed to make room for new construction. The renovated segment included basement-level receiving, supply, and laboratory areas and a 5,000 square foot medical records storage area which could have accommodated a shelter if that had been desired. The renovated floors above were to contain administrative, diagnostic and treatment facilities. Both the new and renovated parts of the building were to be column-supported concrete siab construction with exterior



FIGURE 1 -- Architect's Sketch of Office Facade -- 727 15th Street

masonry cavity walls. The total area proposed was 380,000 square feet of which 267,000 was to be new and 113,000 renovated.

Both of the above buildings had basement areas which would accompodate blast-resistant design as well as their intended conventional functions. In addition, the two projects represented a wide cross-section of the types of problems and impediments which might be encountered in a national scale shelter construction program trying to incorporate shelter design into otherwise typical building projects.




FIGURE 2 -- Preliminary Plan of Office Basement with Shelter

Design Process: Bank/Office Bullding (727 15th Street)

Design Alternatives. The design of the blast shelter was begun in October of 1982. Preliminary design of this blast shelter was quite straightforward. The overall basement plan was simple and there were only a few options to consider. The major consideration was the exact location of the blast resistant wall relative to the elevator and stair tower (see Figure 2). The owner's program for the basement changed several times. For example, one corner went from storage area to a health club/gym. This caused adjustments to the area of the blast shelter. Fortunately, the gym was given up and the space became storage again.

A problem which was a concern for both aesthetic and structural reasons had to do with the ceiling height dimension in the conference/board room. The floor to ceiling heights for the building were tight to begin with and adding several inches for shelter construction made the problem worse. The conference space was a large area which needed a higher ceiling height in order to avoid a cramped feeling. Dropping the floor level was not desirable because that put the foundations below those of the adjacent buildings. This lowered floor level would cause shoring, structural, and construction problems which would lead to additional costs beyond those directly related to the shelfer.

K

Detailed Design/Construction Documents. By February of 1982 three months delay had been experienced in the design of this

project. These delays were caused because the architects had to go through the approval processes of the Fine Arts Commission and the Landmarks Commission.

Serious delays were experienced during the period ending in June of 1982. The architects were kept on hold while waiting for decisions from the owner. The project was speculative and the high interest rates and uncertainty in the financial markets provided a strong incentive for the owner to be deliberate in such decisions as the type of heating, ventilation and air-conditioning system to be installed.

Construction documents were begun in August of 1982, but again the owners were not rushing to complete the project. The construction documents were 90 percent complete at the end of February, 1983. The drawings were finished by the end of May.

Bid Documents. Construction bids were requested for the project in September of 1983. A construction management company directed the bid process, receiving piece bids from subcontractors for various segments of construction such as steel, concrete and glazings. When recleved, the bids for general construction were 50 percent over the developer's budget. This serious problem again stopped the entire process. Alternate bids for the blast shelter and other alternates were not completed at this point. The major problems were the cost of both the steel structure and the marble facade. The redesign of the facade involved resub-


mission to the Fine Arts Commission and additional time delays.

The owners of the development project decided at this juncture for financial reasons that work had to proceed rapidly. In November of 1983 during the redesign process it was determined that construction of the blast shelter would definitely require taking the overall building foundation below those of the adjacent buildings. It was also determined that without shelter construction this would not be necessary. Based on this information an alternate construction bid was produced for the shelter area. The construction estimate of \$175,000 calculated to be \$110 per square foot for the 1,590 square feet designated for the shelter.

At that point FEMA decided not to construct the blast shelter in the office building. The decision was based on the fact that 43 percent of the estimated construction costs were not directly associated with the blast shelter itself. Of the total costs \$75,000, or \$47 per square foot, was required for additional underpinning necessitated by the existence of the blast shelter but not its design. The added depth of both the ceiling and the floor of the shelter required that the building foundation be two feet lower than it would otherwise have been. This added expense was created because the increased dimension put the new foundation below those of the two adjacent structures.

Conclusions. This project (see Figure 3) demonstrated a wide variety of problems which can be encountered in the construction industry. One of the most amusing was that a preservation group called "Don't Tear it Down" opposed the demolition of the theater based on the claim that the open air above the building was an *historic open space*. The mixture of factors involved clearly demonstrates that the inclusion of government sponsored shelter areas in a variety of building construction should be expected to take considerably more time than the ideal fast-track scenario might indicate. This particular building witnessed speculative development occurring during a period of economic recession and escalating construction costs. Time was devoted to obtaining reviews and approval from a variety of boards and agencies. addition to the preservation group and the Fine Arts and Landmark Commissions already mentioned, the project had to be reviewed by the White House security police because of its proximity to 1600 Pennsylvania Avenue. The prime objective of this project, to observe the integration of shelter design into the exigencies of a specific ongoing architectural project, was well met by this building.

The Presidential Point Of View




727 15th Street, NW

ust steps from the White House, 727 15th Street is the epitome of Capital city prestige. This historic address has been fully updated-a distinguished blend of the past and present-with full floor office suites of 3600 sq. ft., dramatic balcony views, state-ofthe-art security and office interiors finished to your exacting specifications.

A development of First Washington Development Group, Inc.

Leasing by
First Capital
Realty, Inc.
232-4220

FIGURE 3 -- Developer's Advertisement with Completed Facade -- 727 15th Street



PRST BASENENT LEVEL FLOOR FLAN

FIGURE 4 -- Hospital Alternative #1 -- First Basement Plan

Design Process: National Rehabilitation Hospital


Design Alternatives. The original design concept involved placing the blast shelter in the medical records area of the existing hospital facility (see Figures 4). Questions arose when AIAF discovered that this section of the hospital was to be partially exposed above grade. Discussion with FEMA led to the determination that renovation type construction was not desired.


A major design objective within the project was to incorporate the blast shelter into an area of the building where the space would still be fully functional on its own right. It was intended that the design not entail any significant structural or construction alterations. The incremental construction costs were to be restricted as much as possible to those for additional material and not for altered design.


The reason stated above led to the rejection of a second alternative location for the blast shelter. That design alternative was the placement of the shelter beneath the lowest parking level in the new construction area (see Figures 5-8). This proposed space was not to be included on the non-shelter construction documents which meant that the incremental costs would have included the entire construction costs as well as additional expenses for excavation and shoring.


Another location was considered and rejected (see Figure 9).

The theater on the existing first floor (north side) had a large










NEH SHELTER HOTTH ELEVATION

1/12/2:


FIGURE 7 -- Hospital Alternative =2 -- First Basement Plan



PRST BASENENT LEVEL FLOOR FLAN

NRH SHELTER


1/12/0.



NRH SHELTER

1/12/

FIGURE 9 -- Hospital Alternative #3 -- First Floor Plan




un-utilized basement which was to be renovated. This alternative did not work for several of the reasons enumerated previously. It would have involved renovation, and significant structural modifications would have been required.

The last concept was placement of the blast shelter on the grade of the lowest parking level (see Figure 10-13). One potential problem with that location was that it fell immediately below the garage ramps. This location was selected and detailed design commenced in March of 1982.

Detailed Design/Construction Documents. In June of 1982 changes to the facade design of the hospital required redesign of the structural column grid. This problem caused delays for the entire project as well as the shelter design.

By August 1982 substantial progress has been made on production of the construction documents. The hospital project was eligible for federal loan monies from the U.S. Department of Housing and Urban Development. Mariani and Associates and their engineering consultants were required to prepare and submit not-to-exceed cost estimates to the HUD program. HUD also required structural and other revisions. Final blast shelter design and analysis had been scheduled for completion by late September in coincidence with the request for construction bids. After submittal of two sets of construction documents to the HUD funding agencies, the decision was made to completely change the building site.



SECOND BASEMENT LEVEL PLAN 1/16:110 1/18/82
NPH SHELTER

FIGURE 10 -- Hospital Alternative #4 -- Shelter Plan






FIGURE 11 -- Hospital Alternative #4 -- Sections & Elevation



PRST BASDIENT LEVEL FLOOR FLAN

FIGURE 12 -- Hospital Alternative #4 -- First Basement Plan



SHOULD BASEMENT LEVEL, MOOR PLAN 0.


FIGURE 13 -- Hospital Alternative #4 -- Second Basement Plan

The new location was on the Washington Hospital Center site adjacent to Children's Hospital at 106 Irving Street, N.W. This decision necessitated a complete redesign of the hospital and took this shelter design back to the initial stage of selecting alternative locations.

By November of 1982 the shelter location was selected (see Figure 14), alternative designs were considered, and structural design calculations (see Figures 16-20) were completed. These preliminary calculations, by Don Neubauer, PE, are included as Appendix A of this report. A preliminary construction bid from Turner Construction Company was received at this time (see Figure 15).

During August of 1983 detailed design and construction documents were completed.

Bid Documents. Construction bids were received from two companies; Turner Construction (see Figure 21) and George Hyman Construction (see Figure 22). Turner's bid for the biast shelter alternate was \$140,000 while Hyman's was \$87,000. Dividing by the 2,300 square feet of shelter area these bids translate to \$60.87 per square foot for Turner and \$37.83 for Hyman. No satisfactory explanation is available for the large discrepancy in construction bids. Unfortunately, FEMA did not have influence on the ultimate selection of the construction company. FEMA's



Turner Construction Company Such Ferrishtania Avenue 14 W Washington D. C. 20004 Teleprone (202) 393-5100

November 12, 1982

NOV 12 1982_

Washington, D.C. 20009 Mariani & Associates 1600 20th St., NM Mr. T.F. Mariani

Subject: NRH Blast Resistant Shelter Study

Dear Mr. Mariani:

We have completed our cost study for the addition of a Blast Resistant Shelter at the ground floor auditorium of the National Rehabilitation Hospital. We value the additional work at \$ 120,000 making the new Farameter Estimate total \$ 19,095,000. (See attached summary sheet).

The study was based on Untitled Drawings prepared by your office dated 11/9/82. The unusually large size beams, walls, columns, and slab coupled with dense reinforcing steel accounted for the relatively high unit cost for the 2,200 sq. ft. shelter.

If you have further question please do not hesitate to call me.

Mery truly yours,


Mores Chomas J. Paci

harf Estimator

at the Childrens' Hospital Campus National Rehabilitation Hospital PARAMETER ESTIMATE

\$ 899,000	3,995,000	459,000	1,498,000	2,481,000	381,000	410,000	1,107,000	402,000	2,179,000	2,047,000	544,000	16,402,000	1,312,000	17,714,000	\$31,000	18,245,000	730,000	18,975,000			120,000	
Excavation 6 Foundations	Structural Frame	Roofing & Waterproofing	Exterior Wall	Interior Finishes	Special Requirements	Vertical Transportation	Plumbing	Fire Protection	HVAC	Electrical	Site Work	DIRECT COST	General Conditions @ 8%	SOR TOTAL	Contingency @	SUB TOTAL	FEE @ 40	LOTAL	PLAST RESISTANT SHELTER \$ 115,000	ASSOCIATED FEE @ 4% 5,000		

FIGURE 15 -- Preliminary Construction Bid -- Turner






FIGURE 16 -- Structural Details -- Sections




FIGURE 17 -- Structural Details -- Basement Plan





FIGURE 18 -- Structural Details -- First Floor Plan






FIGURE 19 -- Structural Details -- Beam Details




FIGURE 20 -- Structural Details -- Column Details

Turner Construction Company 1801 Pennsy vania Avenue 19 A Washington D. C. 20004 Telephone (202) 393-5100

Turner

August 26, 1983

Mr. Thomas Sachs Mariani & Associates 1600 20th Street, N. W. Washington, D. C. 20009

Subrect: Blast Resistant Shelter Alternate National Rehabilitation Hospital

Dear Mr. Sachs:

Flease be advised that our price to add the Blast Fesistant Shelter is One Hundred Forty Thousand Dollars and No Cents (\$140,000,000 and is presented as an Alternate to our National Rehabilitation Hospital GMF Document of June 24, 1983.

The above price is complete and includes General Conditions, Contingency Bonds and Fee.

This price is based on Drawings A-42 and S-13 dated August 19, 1993 prepared by your office. No additional specifications for this work was provided. The drawings are taken to be complete and the price includes no provisions for scope development. We have assumed that this work will be performed consistent with the scheduling requirements of the Project's structural frame. Furthermore, the acceptance of this Alternate will require the addition of one week to the construction schedule.

If you have any questions, please do not hesitate to contact me.

Very truly yours,

TURNER CONSTRUCTION CONTANY

Thomas\J. Paci

RVS TW

FIGURE 21 -- Final Construction Bid -- Turner

THE GEORGE HYMAN CONSTRUCTION CO.

4490 DEL RAY AVENUE BETHESDA MARYLAND 10014

PHONE (301) 994 8100

August 30, 1983

Mr. Theodoré F. Mariani, FAIA President Mariani & Associates 1600 20th Street, N.W. Washington, D.C. 20009

Re: National Rehabilitation Hospital Washington, D.C.

Jear Mr. Mariani:

In accordance with your Mr. Tom Sach's August 19th letter and our conversations with him we offer the following quotations for Alternates #1, #2 and #3 on the above referenced project.

Alternate No. 1 Substitution of Roofing Membrane Material

Alternate No. 2 Addition of Two Elevators

Alternate No. 3 Modify the Structure Surrounding the Auditorium, Audio-Visual/Project Foom, and Storage Room to Function as a Blast Resistant Shelter

Add \$ 87,000.00

No adjustments will be required to our construction schedule if these alternates are included with the base contract award.

Yours truly,

THE GEORGE HARAN CONSTRUCTION CO.

A. J. Clark President

AJC:nm

A subsidian of CEI Construction, Inc

FIGURE 22 -- Final Construction Bid -- Hyman


option was a yes/no decision on construction of the shelter alternate after the National Rehabilitation Hospital had made its decision. The choice turned out to be Turner Construction, the higher shelter bid.


During January of 1984 several other problems occurred. All were unrelated to the blast shelter. There was a change of ownership of the hospital but Turner Construction remained the building construction contractor. There was also a prolonged legal squabble over an adjacent parking structure. Even after the legal disputes were rescived, the construction of the hospital could not be started until a labor strike was settled and construction of the parking garage was completed. The reason for this was that the future hospital site was needed for on-grade parking for the Washington Hospital Center until the parking garage was opened.

1

Ĺ

Construction. Construction of the hospital was finally begun about mid-May of 1984. AIAF menitored the progress of construction on a weekly basis. A series of photographs (see Figures 23-31) taken on those visits follow.






 $\frac{E1 + E - 3}{2}$ -- socital Construction -- Site Preparation






FIGURE 24 -- Hospital Construction -- Site Preparation




A: Interior



B: Exterior

FIGURE 25 -- Hospital Construction -- South Wall of Shelter









FIGURE 27 -- Hospital Construction -- Adjacent Story






FIGURE 28 -- Hospital Construction -- Concrete Formwork






FIGURE 29 -- Hospital Construction -- Footing Poured



Ď





FIGURE 30 -- Hospital Construction -- Column Reinforcing Steel






FIGURE 31 -- Hospital Construction -- Beam Reinforcing Steel

A two-installment construction contract for \$140,000 was written with the National Rehabilitation Hospital, Inc. The first payment for 95 percent was payable at the completion of all concrete work, and the remaining 5 percent at completion of all work on the biast shelter.

Two construction related problems occurred but both were easily resolved. The first problem involved the fact that the shop drawings for the reinforcing steel were completed after the major steel order had been placed. Rather than risk a possible construction delay awaiting the specialized reinforcing steel, the decision was made to redesign the shop drawings to use commonly available steel. A second problem occurred when a concrete tooting was poured from non-shelter construction documents which left the footing one foot higher than it should have been. The resolution was a redesign of the detail to accept a beam above the new footing (see Figure 32). No other significant problems were encountered during the construction. There was difficulty with ground water in an area proximal to the shelter footings, but this was not attributable to the shelter design.

AIAF performed a walk thru inspection of the shelter on September 25, 1984, with representatives of Marian! and Associates and Turner Construction. Construction of the blast shelter was virtually complete at that time. Major observations on the construction process were the following:




FIGURE 32 -- Beam/Footing Connection Details

- o Construction difficulties exist with wall penetrations and beam corners which do not fit flush with other building elements.
- o The scheduling of concrete pours requires careful planning and special attention.
- o Careful planning and additional time is required for building up reinforcing steel during shelter construction.
- o Blast shelter construction did not constitute an extraordinary problem. It was rather one more layer of complexity to be coordinated into the overall process.

K

Use of TR-20 - Volume 4 and Other Design Guidance:

K

٠.

One of the objectives of the project was to evaluate the usefulness of existing stanting design guidance materials. A national program of blast shelter construction which would be necessary to sustain the critical workforce concept would require design guidance materials which were understandable and immediately usable by architects and engineers without prior shelter design experience. Architects, most of whom would not have shelter design expertise, would certainly be involved in the process of incorporating blast shelters into otherwise typical buildings in a large-scale construction program.

in recent years the practice of architecture has increasingly become a problem of leading a team of experts. The architect's task is to communicate effectively with each specialist and ensure that each separate agenda is incorporated into the overall program for the building and addressed adequately as the design proceeds. The ideal design manual would provide the architect with a conceptual overview of what slanting design is all about. Such a document should contain visual presentation of architectural concepts. It is difficult to overstate the importance of visual, graphic thinking for architects.

The findings of the architects and engineers working on this project are that Volume 4, TR 20, "Protective Construction", and the other documents used are inadequate and provide insofficient guidancs. The personnel at Cutts Engineers had no prior shelter

design experience and became quite frustrated, even angry, at some of the difficulties they experienced. Don Neubauer, on the other hand, did have prior shelter experience. On the positive side, Mr. Neubauer commented that Vol.4 TR 20 is superior to other design guidance materials (military documents) he has used, especially when designing something out of the ordinary. Comments from both structural engineers follow at the end of this section (see Figures 33-34).

.

ľ

ĸ

The existing reference documents (see Figure 35) were judged to be more textbooks than design manuals and had other problems as well. Definitions and terminology were inconsistent. Several references were needed to clarify symbology. The layout of Vol.4, TR 20 is quite cumbersome, and requires considerable searching and flipping back and forth. All of these problems increase time of use and consequently design costs.

The ideal design manual would be a single, self-contained reference source. It should present straightforward examples, problems and many charts and tables to assist the busy, inexperienced designer.

NI UNAGER STATE

The state of the s

November 12, 1982

Mariani and Associates Washington, B.C. 20009 1600 20th St., N.W.

National Rehabilitation Hospital Blast resistant design

Following are comments that we offer regarding the use of "Protective Construction" TR-20 (Vol 4) May 1971 in the design of blast resistant structures. There is no particular aignificance in the order of the the manual is competent in presenting a very complex problem in one comments and some come as a reflection about the use of the manual. volume. The comments are not intended to give a negative value to the manual.

- the same. Also it is doubtful that an attempt would be made to harden a structure above ground to act as a blast resistant attructure, so the number of relevant sample calculations need the manual will be used to harden certain areas of a building The examples given are rather irrelevant. It is assumed that and it would be most helpful to have examples that relate to
- The meaning of symbols was not always given when the symbol was first used. This is a deficiency in the majority of technical books. Some symbols are used in the text and not noted in the in searching both backwards and forwards in the manual to refersh ones understanding of the meaning of a certain letter An index would be very helpful. Considerable time was spent list of symbols.

ä

which makes use of the manual time consuming. Sime had two different meanings and which one was being used was not always Some symbols were casually explained further on in the manual

-

4

one is really never certain that the correct definition is being used. If one designs a lot of hardened structures on a frequent have different meanings. This creates an uncertainty in that Sometimes the lower case of symbols was used in the text and In some instances elsewhere in the text the upper and lower case have symbols that upper case in the charts or graphs.

Battonal Rebob Bong Margania and Assertages. 20 Company 12, 1700

ľ

will do so on a very infrequent basis and each subsequent problem would result in beginning again with the studying of the manual. suspected that the vast majority of architects and engineers But it is Besign costs for hardened structures will be very high. sais, these uncertainties resolve themselves.

which were of help. It is doubtful that more than a very small percentage of architects and engineers would be so equipped. Fortunately copies of the principal references were in hand Therefore the manual needs to be more explicit even to the erences were used to determine more clearly the meaning of arithmetic so that the time spent using the manual. some of the symbols.

der these conditions, in order to minimize errors, all symbols, expertise, so those that use the manual will have to follow it "blindly" without fully understanding the design process. Un-Very few architects and engineers these days have the time to devote to design projects that is really needed. The lack of time usually results from insufficient free and insufficient involve referring to other steps behind or shead in the text unless those steps are specifically annotated as to page and formulas and procedures have to be readily apparent and not

taon Hospital that there were many design details that were not considered in the manual. In doing blast resistant design, the problem should be formulated to conform with various charts and tables rather than trying to interpolate the charts and It was noted in the design problem for the National Rehabilita-Structurally dynamic design is much more an art rather than a science. But for most performance. This means having problems that are confortably Such a suggestion engineers and architects, the more science and the less art, the better the solutions will be with respect to costs and within the range of the manual's tables and charts. tables to a problem that is not "simple" should be noted in the introduction.

down with a user and review the manual page by page. Hopefully the authors will not be defensive for if they are not as much value will be driived from the exercise as would be otherwise. The best way to oftain comments on the manual would be to sit

Somet & handmar Denald J. Neubauer Very truly yours,

000 COFY

FIGURE 33 -- TR20 (Volume 4) Evaluation -- Neubauer

. W Electrical Control

K22 8.17

30%

l office.

:: :

The straight of the straight of 1 1 1

March .. 1483

PROTECTIVE CONTINUED TO PARTIE (TH-20 Vol. 4)

REPORT ON THE AREH LIVE

In an attempt to use the Protective Construction Manual (18-20) as a primary and only source to design a blast resistant smilter, it was found that the manual by itself is inadequate. The following are major points in design which, in our point of view, were lacking in the manual and require more affection and elaboration:

1. toading Terms:

manual should elaborate more on definitions of loating and loading on the structure to provide a simplified means of understanding of The loading definitions were found to be very confusing. The loading for the designer.

2. Safety factor:

The application of load factor in respect to utilinate strength design is not clearly explained. It should be noted that load factor in respect to utilimate strength design equal to 1.0.

3. Modes of failure:

(shear, diagonal fension and flexure), the manual should elaborate structure in the three different modes. Also, the importance f choosing the appropriate ductility ratio for each mode of failure. Since the design is controlled by three modes of failure manual should familiarize the designer with behavior of the on approach to design through the three modes of failure.

4. Ductility:

portance of accuming the requires ratio of ductifity for each Since ductility is of great importance in blast resistant It should familianize the designer with the into only a definition and it is mode of failure and a plain why. Also, it should be nated design, the manual should elaborate more on the subject of that the foregla ductility.

to the force of the september to

Ì

ŧ

ľ

fig. Openmer Amalytica

dynamic analysis and explain what results to look for in dynamic analysis. Since this portion of design is the most complicated and time consuming, the manual should concentrate on use of the manual should provide complete practical examples for charts and tables through sample problems.

Stab on grade:

Since design of stab on grade requires careful attention, the minual about explain the procedure and assumptions which should the used in design of slab on grade (floating slab or fixed).

Rebound resistance:

the catculation of rebound steel requires more elaboration.

Preliminary & final design:

In final design calculation, it should be noted that convergance of only ductifity ratios for flexure mode is required and ductility ratios used in shear and diagonal tension are to provide only a means of checking resistance for those modes of

9. Typical details:

lypical details & spacing for web reinforcing should provide is allowed to have large deflections, the presence of web reinfercing also provides a means of securing top and bottom rein-4d from support. It should also be noted that since the stab quidance for size and spacing of ties beyond the distance of forcing in place during deflection and rebound.

O. Charts:

should include all the charts and design aids available for blast Since charts and design aids in blast resistant design can save the designer a considerable amount of time, the manual resistant design.

resistant design. However, it is inadequate and impractical to be used as a design manual by an average structural engineer, especially for in general the manual is an informative text book in the field of blast one with no back ground in dynamic analysis and devign.

۔ د

REFERENCE DOCUMENTS

TR-20 (VOLUME 4) PROTECTIVE CONSTRUCTION. Defense Civil Preparedness Agency. May 1977.

DESIGN OF STRUCTURES TO RESIST NUCLEAR WEAPONS EFFECTS. The Committee on Structural Dynamics of the Engineering Mechanics Division. Engineering Practice Manual No.42, 1962.

THE EFFECTS OF NUCLEAR WEAPONS. S. Glasstone & P. Dolan (eds.). Prepared by U.S. Department of Defense and U.S. Department of Energy. Washington, DC: U.S. Government Printing Office, 1977.

MAXIMIZING PROTECTION IN NEW EOS'S FROM NUCLEAR BLAST AND RELATED EFFECTS: GUIDANCE PROVIDED BY LECTURE & CONSULTATION. NTIS Accession Number AD/A 039 499, September 1976.

PRINCIPLES AND PRACTICES FOR DESIGN OF HARDENED STRUCTURES. N.M. Newmark & J.D. Haltiwanger, Department of Civil Engineering. Technical Document Report Number AFSWC-TDR-62-138, December 1962.

REINFORCED CONCRETE DESIGN. Wang & Salmon. New York: International Textbook Company, 1973.

SLANTING IN NEW BASEMENTS FOR COMBINED NUCLEAR WEAPONS EFFECTS: A CONSOLIDATED PRINTING OF FOUR TECHNICAL REPORTS. NTIS Accession Number AD/A 023 237, October 1975.

FIGURE 35 -- Existing Reference Documents

Model Test:

Two models (at one-fifth scale) of the blast shelter at the National Rehabilitation Hospital were constructed. These models were built by Waterways Experiment Station under a separate contract to the Federal Emergency Management Agency. These two models were exposed to a simulated nuclear explosion at White Sands, New Mexico, in July of 1985. The following photographs were taken in New Mexico at the blast test (see Figures 36-45). One model was placed at a location so that it was exposed to the 15 psl overpressure for which the actual shelter was designed. The other model was placed at a location so that it was exposed to 50 psl overpressure. No above-grade structure was included on either model which further increased the vulnerability to structural damage, because this was taken into account in the actual design calculations.

The Salar Salar Carlo Salar Salar

The model exposed to 15 psi overpressure suffered no apparent structural damage (see Figure 43). The model exposed to 50 psi overpressure suffered only minor damage in the form of hairline cracks. The cracks may be seen on the photographs (see Figures 44-45). The cracks were traced with a marker to highlight their location, but the result is that the damage appears more serious than actual. The apparent conclusion is that the design guidance provided by "Protective Construction", TR 20, (Vol.4) leads to partial overdesign for shelter structures intended to withstand 15 psi overpressure.





FIGURE 36 -- Blast Test of Model -- Front & Side of Shelter



FIGURE 37 -- Blast Test of Model -- Rear & Side of Shelter



FIGURE 33 -- Laterior of Hospital Shelter









FIGURE 41 -- Hospital Shelter at 50 ps. Level -- After Back Filling



HGBEL 42 -- View of Hospital Shelter at 50 psi level



FIGURE 43 -- Post-Blast View of Hospital Shelter at 15 psi Level -- Showing No Cracks




FIGURE 44 -- Post-Blast View of Hospital Shelter at 50 psi Level -- Showing Hairline Cracks on Roof




FIGURE 45 -- Post-Blast View of Hospital Shelter at 50 psi Level -- Showing Hairline Cracks

CONCLUSIONS

٠...

X.

1

R

ſ

Conclusions can be drawn in regard to two major issues which were investigated.

- o Feasibilty of incorporating blast resistant shelters into otherwise typical building projects.
- o Adequacy of currently existing shelter design guidance materials.

No conclusion as to the cost implications of a large-scale blast shelter construction program can be drawn from this effort.

Blast shelter construction as an add-on proposition to structures being built for totally different purposes is a viable concept. It is a manageable task which can be accomplished rather simply given adequate financing and proper planning and forethought. Given the significant number of variables over which FEMA has no centrol, however, it would be extremely difficult to predict precisely when the construction of any particular shelter might be completed. There was a significant increase in anti-nuclear sentiment during the course of this project which might also tend to make the task more difficult.

Existing design guidance is considered inadequate for use in a large scale shelter construction program. The materials used for this project assumed prior knowledge, provided more education than assistance, and were difficult and taxing to use. The information and recommendations which the documents provided were proven to be accurate, though apparently based on highly

conservative assumptions.

RECOMMENDATIONS

٠..

L

Any large-scale shelter construction program should be formulated in recognition of the exigencies of the construction industry, financial markets, and the whims of public opinion relative to nuclear issues.

No such national program should be contemplated prior to the preparation of simplified, straightforward design manuals for architects and engineers as well as generalized educational materials for building owners and others involved in the construction process.

APPENDIX A:
PRELIMINARY STRUCTURAL CALCULATIONS -- HOSPITAL SHELTER

```
TRY 30' WALL BEAMS WITH 10' 4980UNS
```

15 PS = 15 + 14 + 2160 PSF.

BEAM LOSOILLY = 2160 410 = 21600 %

M=1/8 121600 x 30.0 2 2430 14

As= 2430/4021 46 = 13.14 m2 Pa 13.14/24146 : 0.0119

TY CEM 121' 46" (CHALLES TO 2018)

Ku= 0.91 x 0.011q x2 + x 4+ x 52000ps1 = 2383" v4 2430 12" 10'5 As=16x1.27 = 1524m"

94(4) = 8[0.0119 (1-6.13+0.0114) + 0.0025 (1-6.13+0.0025)] 7600 (+4)2= 116.1 PSI 94= 116.1 x 24 = 23.2 ps > 19 151

:NCREWE VER 47660 444 69" - 4x0.70 x12 - 1.07 - 9 = 1.07 = 0.0049

7= (1+ 0.0025) x (1000+2x0.004x4200) 10.0119 x3750 x (11 x24 -12.7 ps <15 H4.

MOCH SEAM TO 30" 444@6" PU = 0.80 = 0.0044 15.24 = 0.0115

7+ = (1+0.0015) A(1000+2.2.004441000) [0.011543750 A(44) 430 = 15. Lps1 = 15.0 ps1 0.K.

J= 30 x 2160 = 324 20 = 245 psi

d/L: 41/360 = a122 < 0.20

NRH- ELLET HIELTER

kieusauer • sommi, com 4. Bulyres

NOV 15.82 (1)

7140 4PAN 10-0"

M= 10 x 2160 x 10.02 = 21600 16/FT. A5 = 21.6/4.02 x1:2 x 6.5 = 0.69 wi2/FT

P= 0.69 /12x6.5 = 0.0085 70.005

REXUPOL YIELD RESISTANCE FOR COMPRESSIVE STEEL USE 0.0086/2 = 0.0044INTERIOR SPAN $\frac{1}{4} \left(\frac{4}{5} \right) = 8 \left(1 - 6.134.0.0088 \right) \left(0.0088 + 0.0088 \right) 72000 \left(\frac{6.5}{120} \right)^2 = 28.1 \text{ psi} > 15.0 \left(\frac{4}{5} \right)^2$

EUD GROW

94(2) = 8(1-6.13x0.0088)(0.0088+0.00++)72000(6.5)=76.9 PS1

90(9) = 0.4413000 (0.0542 /1-0.0542) = 75.6 psi < 15.0 0.K.

DAGOJAL TENSION

$$\frac{1}{12} \left(\frac{1}{2 + \frac{0.0025}{0.0086}} \right) \left(\frac{1000 + 2 \times 0.0026 \times 42000}{12} \right) \left(\frac{0.0088 \times 3000}{0.0088 \times 3000} \times \left(\frac{6.5}{12} \right)^2 \times \frac{12}{12} = 8.2 \text{ pol} \times 15.0 \text{ H.G.}$$

TEX 9" 460 da 71/2" p= 0.63/12175= 0.0070

TRY HIGHER STEEL STREYS

TEN 4000 psi concrete

COLUMN

OYNAMIC LOAD = 10'x12" x15 PS1 = 21,600" x 30' = 324.000 "/BM CERCTION

21324" = 648" x 2 (LOADILLY FRETCIE) = 1296"

TEXT COLUMN 30" (TOMATCH BEAM WIOTH) x18" 4% REBORD = 0.040x30x18 = 21.6 m²

18410 = 1841.77 = 22.86m² p = 44.84/30x18 = 0.0423



0.85 (400x1.25 (30 (18 + 22.86 (72000 = 3441))

0.333 (30 (5000 x 16.67 + 11.43 (72000 x 13 = 1842))

P + 3.141.5 (P = 1 P+ 0.312 P= 3441 P = 3441/1.312 = 300 3 "W"

3441 1142 P = 300 3 + 0.70 = 2102 " > 1296"

HOVEVER, IT IS RECOMMENDED THAT SPIREL TIED COLUMNS BE USED FOR REST DESIGN
TRY 18" \$ COL / 8 * 10' >

FROM CREST @ O. It PU= 743 " X 1.2 (DYHAMIC STRESSES) = 892" CLOSE ENOUGH

4100E12 SPAN 200'

de 134 = 36.1 USE 80" (18"x 64" 5m)

An = 1134/4.0241.2 x 80 = Eq4 mi MILL 65 = 0.005 x 18 x 80 = 7.2 mi 6410 = 7.62 mi p = 7.62/18 x 80 = 0.0057

Av=0.0025 (18x12=0.54 m) 2#6=0.62 m) Pu= 0.62/18x12=0.0029

PURE SHEAR d/L = 20/20 = 0.333

9. (4) = 0.55x4000 x 18 = 206.3 x 18 = 15.5 ps 7 15.0 ax

FLEX.RE

94(2) = 8(1-6.13 +0.0053)(0.0053 +0.0053) + 12000 (20) = 6564

END SPAN

44(4)= 8(1-6.15 +0.0053)(0.0053 +0.0026) x7200x (60)2=480.2

DIAMONAL TEUSION

$$\frac{q}{4\pi} = \left(\frac{1}{1+0.0053}\right) \left(\frac{1000+210.0025171000}{1000+210.0025171000}\right) \left(\frac{2005344000}{240}\right) \times \left(\frac{80}{240}\right)^{2} \times \frac{13}{120} = \frac{302853}{120} \times \frac{13}{120} = \frac{30285}{120} = \frac{3$$

HATURAL PERIODS

$$\frac{4480}{850,000} = \frac{1}{350,000} = 0.0266 = 0.0266 = 0.026 =$$

7-...

3EAM

$$M = 3$$
 $\frac{1}{T} = \frac{1.5}{0.004} = 25$ $\frac{2m}{mq} = 0.85$ $\frac{1}{T} = 10$ $\frac{m}{mq} = -0.25$

YOLL

LIRDER

1 /4 = 3

wall

$$M = \frac{1}{8} \times 2160 \times 13.0^{2} = 16.63^{16} \qquad d = \frac{15.63}{0.579} = 8.87^{-} 12^{-} \text{ which delon} \qquad \Delta 5 = 45.63 / 4.02 \times 1.241$$

$$P = \frac{10}{12410} = 0.0003 \qquad d/L = \frac{10}{156} = 0.064 < 0.20$$

$$49 = \frac{10}{156} = 0.0003 \qquad d/L = \frac{10}{156} = 0.064 < 0.20$$

PURE SHEAR

Net- BLAST SIELTER

PERURE

EESISTANCE

The state
$$(q_{ij}) = 20.9 \text{ PSI}$$
 $n = -0.13 \text{ My } (0.50 \text{ B.K.})$

SHEAR $(q_{ij}) = 15.6 \text{ PSI}$

DIAM. TELL $(q_{ij}) = 31.5 \text{ PSI}$

EEAM, FLEXURAL
$$(q_{ij}) = 29.5 \text{ PSI}$$
 $\frac{1}{4} = -0.41 \text{ } = -0.4$

APPENDIX B:

FINAL STRUCTURAL CALCULATIONS -- HOSPITAL SHELTER

NATIONAL REHABILITATION HOSPITAL BLAST SHELTER

CALCULATIONS



AUGUST, 1983

Consulting James de 4. Olas suiter Structural Madison By Check Date Washington as delec me L215' FC = 3000 PSI Fdc = 3750 PM Fdy = 72000 issince it for excll MODE of followed it=0.1 , -legues PEP M =10 e) THE SHERE 11-1.3 of omenal federal N = 3.0 N = 1.5 Py (0.0025 citalér resures resistades por rest mos Pa pickuice 9x = 15/(1-1/2+10) = 15.6 PSI SHEAR 24 = 15/(1- 1/24/3) = 24.4 PS DID (RN. 97 - 15/(1- 1/13) - 16 Pil Py > 0.0025 9/ = 15/(1-1/2) - 21.5 PM PVL0.0025 DEP! Il SDES ON SHERE No INCLINED Sheet b/2=1.0 9V=144=3000 - 4/2 x.44 -24.4-24.4 de = 1320 de de -.019 d= .019x 13x12 - 2.9 IN (MIN) DEPH BASED ON PLAYURE END SPAN 9x = 7.3(-02+.01) x72000 (4) = 15:8 15.5

.*

Location しいいいいいいい Structural Check Date de 13x12x.03v= 4.9 dus FOR LE SPA Note un d'ain- 12° 1 - 10 - 06 ·08 2/ 15.6 7.3% (P+P) x72000 · 01 = 15.B 7.3 x/P, P) x 72000 15.6 = 5256 x (P+P) P=.003 USE Pap mind of .005 CHECK FOR INTERIOR SPAN ~ 158=9= 7.3(p-+p) +7-000 (d) $\frac{d}{L} = / \frac{15.6}{734.01872000} = .055$ 0'2 .055 x 12 x 13 = 85° L12° O.K WALL FOR END. SPON d - / 15.8 7.3x.0075×72002 d = .06. x1-x13 = 9.4 </2 CHEEK . DIAG TRASION 9/2 3.5 /3000 (.08) = 15.34 L 22.5 PSI 22.52 [1/(2+1)]/1000+(cfy x72000)] [.005x3000 x .06 x [1+1:5]

225 - 20.5. + 2944PV - 20007 < .0015 USE /4 MIN 2 .00-5 WE #3 (10) $.\cos 2 = \frac{Av}{10 \times 3} = .08$ 1) colociale datuent preion L-13K/22 156 Pr.005 pr.005 d2/25 SEC FOR END grid 7- 1×156 2 103 SEC FER INT. = 111N) SINGLE PRIMELIE REPRESENTION; CHECK REQUIRED RESISTANT 16/ 1.55 = = 17.5 END SPAN PLEXUEN: UZ 10.0 To - 17.5 Pag- 21.01 FIGURE 4-13 <u>Id</u> = 2.3.3 9 REAVIRED 2 15.15 PSI F = 17.5 12.65 PARE SKIR 11.21.3 上==50 h 9 2 15 - 23.06 PSI

Madison 9/2 15 - m.7 seviedes == 7.3 (.005 + 005) x72 cco x.05 = "17.6) 912.44x3000 (105) =1148 1957 15PS1 2006. Alson of = [1/(2+1)][1000+2x.0025x72000] \.005x300 x.08 x 25 = 27.8 PII) 22.7 PII OK Note JAR PROVIDED RESISTENCE IN RACH MODE IS GREEKER THAN REQUIRED = 17.5 £ 23.3 RG2 RE. RESIGNAL - 16+336-605 PSI REBOUND RESISTANCE - 734.005 x72000 x.05 -10 USR #7 610 00 183 7. - C 3". 9/v

	James Madison Cutts	Consulting Structural Engineers Washington DC		Location A/ASLI () C. By Check Date K.O. 7/20/6) Sheet
N	1 1/2 3.1	office Expens	r	Sheet s/ig
	BESM O	resul	L= 30-5	fer 3000 psi
•	4			/ fdy 272000 191
	الا سعاد بر	KAR: 4-19	ئىر	elaxure ar lo
		/		Pr) 0.0025
			11 = 1.5	Py < 0.00=5
ţ	SHO DEF	o long z	150×14 (1-	(1) 2:1. PSI Fixture
		-	150 × 14 (1 -	11 = .746 PM , LOR 3/ 5/2
X	516	i tentro d	150014 (1- 1705 1 (1-	$\frac{1}{6}$) = 1.0 1.1 Ps/ (v < .0005)
•	9,5	= <u> </u>	_ = 19.V	6,1
	, fy	= <u>/3.75</u> /- <u>/.</u> 6	25,5	<i>031</i>
•	97	- 16 1-16	19.~ P	si /b >0.00-5
	39	1- <u>15.8</u> 1	-= 23.7 /3/	142.0025
•	DEPLY BATE	וצ אים ח	Kac	
	Evz 25.	$5 \times \frac{13}{3} = \frac{d/c}{1-d}$	110 - 110 L	5-11050/L= 1320 d/
· · · · · · · · · · · · · · · · · · ·	•	9.	12.09	5 - 110.50 / 2 = 1320 d

Consultina 11 Was mother CHECK BEAM DEPIH FOR GF & 27 19-13 = 7.3 x. c2x72000) peptil posts and prosedul Estado 1550ME /2 .005 $9/235/3000(.09) \times \frac{3}{13} = 3.98$ PSI 237 NR TRY PY C. OURS OF REQUIRED = 23.7 PUI 23.7 = [1/(2+005)][1000+2/V x72000 x(.09) x 3 23.7 - (.44) (1000 + Pyx144000) x 7.75 x.01x.23 23.7 = 7.84 + 1129.4py Pv = .014 .0025 . 2 > .0025 & REQUIRED = 19. V PSI 19.2. [1/(2+.005)][1000+144000Py] x J.02x3000x.09x3 19.2 = 7.64 + 1129.4 Py Py . . olo1 Ay 2.010/x36x6 = 2.16 IN $P_{y} = \frac{Ay}{b's}$ #7 #7 e 6° de roe 12-0 TRY d-45" d/cenis:10

TRY d-45" d/cenis:10 192/1/(2 1.305)/(1000) 1/000) x/.000 x.1167 x 3

N.R.V SIAL STELL Consulting James Structural Mad:son Engineers Washington Check CHECK DEPILL CONTO 19~= 10.7 + 1542.4 Pu Pv - B.5 = . 0055 At 2.0055 x 36 x 6 = 1.19 IN · USC 百=506 de Note nojust P FOR d = 43."

Se REQUIRED = 19.0 PSI \$\frac{1}{2} = .1167 $ais6 = \frac{62.3}{5056000} =$ P2.0115 As = .0115 x 36 x 42/ = 17.3 IN USK 12 = 11 Bo. Proper 111: 105 x 36x -1-- 7.56 USE 6 # 10 10p DYNAMIC ANALYSIS OF BEAM L=2011X12=368 1N P=0.0115 T = 368 = .0681 SEC. To .7 SEC. T = 10.3 RESOUNO $u = \frac{1}{0.06} = 15.3$) lo use 10 v' = .25 $v' = 7.3 \times .0124 \times 720001.1$ 8F = 7.3 ×.0/24×72000 (.1167) × 3 -20.4 1 = - · 225 x 20.4 - 4.6 PSI

Madison Cutts	Structural Engineers		N.R. H.	Bl 26 319/11	, <u>L</u>
	Washington CC		By Check	1) 27/87	***************************************
BEAM DESP	L C-N1/2		Sheet 8/	,	
PROVIDAD	resounds	RESISLAND	ic.		~
12 7.3%.	005×72000(.116	$(7) \times \frac{3}{13}$	8.26 11)	46 M ok	
REQUIRED	REISTANCE		PROVIDED		
FLEXURES:		± = 103	F16 4	-13	
1 2.85		16 = 18.6 .65			
PROVIDED - PURE SI	ER = 204	PSI > 13.8	3 ok		
Pm 2.65			I = 10.7		
8v - 15.8 .65		ادح			
PROVIDED	ey 5 KNS:2N	5×3000 x.1	161 x 3 = 44.	م ديد (ادم م	<u>;</u> /
DIAL LIL (RNSON	T = 10.3	K23.0	85-16.6 P	٥!
ET 1804 10:	ED 2 /1/(2+=	005 01(4) X(100	04/44000000	157) × /1012423-	, ご.
	× ·1/67 ×	$\left(\frac{3}{13}\right) = 1$	14.8 131	<18.8 12 H	1
RROESIL N	BM TRY	6m 2	- 6 × 4'-0"		
d/ 2- 46 30×12	/28	DELERMI	IN P		
19.2 13 =	7.3 x / x 72000 X.		8611.4/2		
	USC 7 01	15	Pr.0145	•	

NRH BLAS SHELTER Madison Structural Cutts Engineers Washington By Check Date K.R. 7/27 PURE SHEAR BY INSPECTION OF ? CRUNED DIA (ENSION = 192 PSI /2.015 0 -18 192 = [1/12 + .005) 1000 = 144000/21 × 5.01543000 × .128 × 2 19-2 = 7.2 + 1043.5px 11.0115 BY- .0.15 x 24 / 6~ 1.65 TRY BM 4-0×4-00 19:0x/3 = 7.3x/x7200x128 P2 .0072 115K Pr. 2075 19.24 1/(2 + .005) (1000+14400) PVX (000×125 x 1/3 19.2 - 8.96 + 1291.3P. Prz. 0069 AV2 .0069x46x6 2 V.0 111" TRY BM. 36444 W/ INCRENCED PY 19.2 - [1/12 4.005] x (1000 + 144000) x V. 0/24×3000 × 11672 x 3 19.2 - 8 + 1146.5 Py Py2.0098 AUZ . 0096×36×6~2.11 IN UNRENCITIV USE BM 36 × 45 WILL Pr.02 9/2 /1/2 -005/x/1000 + 144000 x. 0057) x/. 02 x in x 1/67 x 3 2/2 19.7 MI 18 8 BY At

N. R.H. BLOW SHELLER Consulting James Structural Madison Engineers K.o. 25 = .7 SEC FIG. 1-14(a) M2 -1 = 6.67 Pm 2.96 - 2 -7 ~ 13.05 FIRSURRY 0 x REQUIRED = 16.3 1911 12 PROVIDED = 7.3x.00x72000 x.1167 x = 33 (31) 16.3 01 PURE STEAR 12 1.3 1.5 ?1 = 15.8 = 24.3 PSI RELUKED 21 /20010ED 2 . 444 3000 (-1167) x3 = 40. ~ PII) 24.3 06 DIA. (KNSKN 1123.0] - 13.6 Pm 2.65 ? REQUIRED 2 16 213.6 PSI 9 12:0x 10:00 - 19.7 PM SEE SUT 9 CURCLE RESOUND SZ. 1 SRC. FZ 13.05 MZG.(.) -1-7.805 2.25 > .2/ O.K : 36 HIDE X 45 DEEP 5011 Sigel = 20 # 11 IN THO LAYERS 10p SIGEL = 6 # 10 TOP USE dz 1. Ter COR CR - PLAK COM -16.1. dr. 116 10755412 =39.9

1

	James Madison Cutts	Consulting Structural Engineers	Job IV.R.H. BLASSHAISER Location
		Washington DC	By Check Date K.O. 7/18/63
	itall pros	12 N	Sheet 11/18
			4'-6' Prin = 15 psi 7 Bc
		.•	3750 /cz 3000 p.
	1 /		
	RESULTED)	RESTANCE =	
		ê	y = 24.4 Gi
		0	7 = 18 PSI PSI PSI
ŕ		0 2	(= == 5 ()) Py L. co=5
	34 M 64	iso of share	·
Ė	gy = .	551'c of	9 - 24.11 = · 0/5
	d015,	(14.5 x/2 = 2.6	<i>!</i> *
Œ	PROLL!	SAIRD ON FLE	12 /= 1005 /2.0025
		173)(.005)(71600)	_
) 	dr.a	775 ×14.5 ×12~ 13.	5
	Tay	/2.0/ <u>0</u>	2/15.5 1 7.34.01×72000
	d = . c	548× 14.5×1V= 9.5	use Tali dalo"
i	CHRCK	DIA. TENSION 9	-2 3.5/3000 × .0575 = 11 PI
	95 =	(2 + .0.0015)x(10	00) x \(.61x3000 \times .0575 = B. PSI B 59CCI
		USK WE	B SICCI

A TO THE CONTRACTOR OF THE PROPERTY OF THE PRO

. R. H. Blan sitelier Madison Engineers Check WALL DRIVEN CONTO Pr 4.0025 1121.5 21=20.5 PSI P=.con 225= [1/(2+ -0215)] (1000 × 144000 2) \.01×3000 ×.0575 225 = (.444) (1000 x 144x00 /4) (5.4) x.0033 22 5-7.9 = 1139 PV Pyr.0/26 >.0025 81 xc2 = 18 PS 18 = [1/(2 + .0025)] (1000 x 144000 Px) x [.01x3000x.0575 16 = 79 + 1139 Pr /v = 10.1 2 .0089 T= 14° $\frac{d}{L} = \frac{12}{12.111.6} \times .069$ DRP[H FOR PURE SHEER SY INGO. O.K. ASSURE /4 .0005 423 87 RERZ 16 PIL 18 = [1/12 +.0026] x/1000 x 144000P,) x [.0065 x3000 x.069. 18 = (-419) x (1000 x 144000, 2) x .021 18 = 8.6 + 1268 //y Pr = 9. ~ -. 0073

.

d. R. H. Blat STICK Madison Check stall nested nydome adalysis Halund meno L- 14.5×12-174 T= .7 SEU Fis. 2-14 & = 1.95 CHECK RESOUND = = 9.5 12 -15/10 1/2.25 P2.0025 -.36/.225 016 USE 10 CHIEL RESISTANCE IN EACH MORE FLEXURE 4210 = 29.5 [m-1.05 9 - 15 - 142 < 15.8 ok PURK SHEAR U. 1.3 = -95 Pm -.66 by = 15 - 22.7 By INSP. ok DIA. 12d. Mrs \$ 19.5 Pm - .85 grea = 15 = 17.6 >18 ok WALL SUMMARY IZ14" dz 12" 45R 46 @ 10° d- 11. As = . 0065 x 12 x 12 = . 936 MSR \$ 5 € 10° 0/4 0.F AS'2 .0025 ×12412 - .36 BY 2.0073×10×3 2.219 USR- # 4

N.R.11 BLOST SIELSAR Madison Structural Engineers Cutts Location WASH. Washington WINI MELK ERE AXIAL IMAN D 1' stap of wait Prz.0065+.v25 22.009 Par (.65 y 3750 +.009 x 72000) x 10 Paz 38355 # P= 1x6.5x12) x16 = 1248 # mu 21 / 1/2.156 Pa = 1246 2.0325 sy wasterial will of WALL FOR BEAM REACTION TRIB BICKA- 15 x 13 x 12 - 28050 DESIGN COAD-2×16×28080 = 900 K ASSUME M21.0 ASSUM 3 ET OF WILL UNDER BEAM. Pa 2 36×36.42 1382 K 1382 Mu 21.0 Pfy 2.156
FROM FIGURE 3-22 P2-7>.65 O.K 1 = 100 = .65

N. R. H P. M. SHELLER Madison Structural Cutts Engineers Location WASH DC. Washington Check Date 7/19/62 Sheet COL DESIGN 900 NOTE: COL. BRACEDBY ASSUME Pr 900 - (.85x3.75+.00.x72) AC AC = 900 = 194 IN z rdc = dc=15.7~ 1N de = 194x 4 = 247 / 1 /2 .0/ Ac = \frac{900}{3.91} = 230 /N de = 250×4 - 292 Use dez 16 SPIRAL STREET ROLS 13- . 45 (A)/Ac -1) (ic/eu) 1/3 = 17 d = 3-14/20 = 160 15- .45 (560 -1) x 3/2 2.01 12.12 ffv 2.12x3/200.01 say whi

N.R. H. BAI SHELLIER Madison Cutts Engineers Check Sheet COMPERSSION STEEL 1/2 .d 2 BS FS22.54 Stick ARRA, USED FOR GEN REQ. POR USE SAME SEEL RED. FOR NITH SPIRAL TIES =3 DESILIT STRIP ON THE SDES OF MOR TO CHERY FOOR 45C WID! 2 3'-0" L= 14'-0 FLRYURR DIA. ERN. 4230 PV).0025 PURK SHEAR N 21.5 / C. CO25 95- 15.6 /5/ 9, 225.5 PM ?- 192 Pi 1/2025 2 = 237/1 Py 2.00=5 profil sesses en stark ? v 2 25.5 × 3 = di v. U. × 3002 de - 765 .055 1300 de = 76.5 -76.5 de DSIME P- .02 DEPIH ERIVINED FOR PLEXURE 15.6 x3 = 7.3 x. ov x 72000 (4)

N. R. H BLAIL HELSER Consulting Structural Madison Engineers MASI D. C.

By Check Date

8/1/63 Washington DESIGN WALL TO CARRY TOOK LOAD DEPLY per DA. TENSION ASSUME 11.3 P).0025 87 = 19.2 PSI \$2.07 19.2 [1/(2+.005)] 1000+144000 Py 7x J.0243000 x.07 x + 192 = (.44) (1000 + 144000 Py) (.013) 19.2 = 5.56 + 601 py 19.2-5.56 = 80/fy Pr = 13.6 = .02 < .0025 .0025 x3x12=.09 NOTE WEB REINF USED IN WILL 1524 63 0/2 by dome adaysy Later 12-168 in Paron T= 168 2-17 SEC FIG 2-14.
425000 × 1.02 × 1.0

T - 17.9

T - 17.9 1 - 1 = 6.66 CHECK RES: UND 1/1 2 .18. \$ 2 .005 = .25 > .18 O.K CHACK RESISTANCE FOR EACH MODE = - .97 FLEXINE 4 = 6.66 = = 17.9 € 2 15-215.46 < 15.8 O.C PURE SHEER 12-113 == = 17.9 Par - . 65 10 = 15 - 23 PM 235.5 OC

James Consulting 6. 61 sile See Madison Structural Cutts Engineers 2.61 Washington DC By Ch Check Date WALL STOP TO CAPRY DURK LO Sheet DIA. TEN. 123 ~ 17.9 81 - 15 - 2 17.6 Z 19.V More resistance province in each more is arealer that resistance recurren SUMMORY d 2.07 d 2/2 = 14" .02×12×1221.88 NES SIREL SONE A USA 226 R Γ.

DISTRIBUTION LIST

Federal Emergency Management Agency Research Office Attn: Assistant Associate Director National Preparedness Programs Washington, DC 20472

Assistant Secretary of the Army Attn: Assistant for Research Washington, DC 20306

Defense Technical Information Center Cameron Station Alexandria, VA 22314

Oak Ridge National Laboratory Attn: Librarian P.O. Box X Oak Ridge, TN 37830

H.L. Murphy Associates P.O.Box 1727 San Mateo, CA 94401

Los Alamos Scientific Laboratory Attn: Document Library Los Alamos, NM 87544

The RAND Corporation Attn: Document Library 1700 Main St Santa Monica, CA 90401

Emergency Technology Division Oak Ridge National Laboratory Attn: Librarian Oak Ridge, TN 37830

Director Lovelace Foundation 5200 Gibson Blvd SE Albuquerque, NM 87108

Commanding Officer
U.S. Naval C.E. Laboratory
Attn: Document Library
Port Hueneme, CA 9340!

Air Force Weapons Laboratory Attn: SUL Technical Library Kirtland Air Force Base Albuquerque, NM 87117 Samuel Kramer
Office of Federal Building Technology
Center for Building Technology
National Bureau of Standards
Washington, DC 20234

Director
U.S.Army Engineer Waterways Experiment Station
P.O.Box 611
Attn: Document Library
Vicksburgh, MI 39180

Director
U.S.Army Ballistic Research Laboratory
Attn: Document Library
Aberdeen Proving Ground, MD 21005

Ed L. Hill Research Triangle Institute P.O.Box 12194 Research Triangle Park, NC

Applied Research and Associates Attn: Cornelius J. Higgins 2601 Wyoming Blvd. Suite H-1 Albuquerque, NM 87112

Dr. John Cockayne Senior Scientist Science Application Inc. 1710 Goodridge Dr. P.O. Box 303 McLean, VA 22101

Jud Leech BDM Corporation 1801 Randolph Road SE Albuquerque, NM 87106

Gard Inc. 7449 N. Natchez Ave Niles, II 60648

Donald Bettge
Office of Civil Preparedness
National Preparedness Programs
Federal Emergency Management Agency
Washington, DC 20472

W.L. Huff USAE Waterways Experiment Station P.O. Box 631 Vicksburg, MI 39180 Director
Defense Nuclear Agency
Attn: Technical Library
Washington, DC 20305

Carl Wiehle Defense Intelligence Agency Attn: CKW DB-4C2 Washington, DC 20301

C. Wilton Scientific Service Inc. 517 East Bayshore Dr. Redwood City, CA 94060

Secretaire d'Administration Ministere de l'interieur Direction Generale de la Protection Civile Rue de Louvain 1 1000 Brussels BELGIUM

Canadian Defense Research Staff Attn: Dr. K.N. Ackles 2450 Massachusetts Ave. NW Washington, DC 20008

Director Civilforsvarsstyrelsen Stockholmsgade 27 2100 Copenhagen 0 DENMARK

Direction de la Securite Civile Ministère de l'Interieur Rue Ernest Cognac 18 92 Levallois Paris FRANCE

Bundasministerium des Innern Graurheindorfer Strasse 198 5300 Bonn 1 WEST GERMANY

Ministry of Social Services 11 Spartis Street Athens GREECE

Almannavarnir Rikisins Reykjavik ICELAND Stato Maggiore Difesa Civile Centro Studi Difesa Civile Rome ITALY

Civil Emergency Planning Directorate North Atlantic Treaty Organization 1110 NATO BELGIUM

Jefe, Seccion de Estudios y Planification c/Evaristo San Miguel 8 Madriu 8 SPAIN

Dr. Bengt Vretblad Royal Forifications Administration Fack S-63189 Eskilstuna SWEDEN

Ministero dell'Interno Direzione Generale della Protezione Civile 00100 Rome ITALY

Directeur de la Protectio:: Civile Ministere de l'Interieur 36 Rue J.B. Esch Grand-Duche de Luxembourg

Directeur Organisatie Bescherming Bevoling Ministry of Interior Schedeldoekshaven 200 Postbus 20011 2500 The Hugue NETHERLANDS

The Head of Sivilforsvaret Sandakerveien 12 Postboks 8136 Oslo dep Oslo 1 NORWAY

Servico National de Proteccao Civil Rua Bela Vista a Lapa 57 1200 Lisbon PORTUGAL Civil Defense Administration Ministry of Interior Ankara TURKEY

D

Home Office Scientific Advisory Branch Horseferry House Dean Ryle Street London SW1P 2AW ENGLAND